

**EN**



### **Product Safety Recall**

**Due to an assembly deviation occurred on a specific production batch manufactured during January 2014, owners are invited to contact their point of purchase.**

### **Product**

**It concerns luminaire type PowerPlus - POWLi233 having the following serial number;  
15-01-2014/131237/xxx**

**The serial number can be found on the product marking plate.**

### **Hazard**

**The sealing method of the luminaire may have an assembly deviation, and may therefore allow some water to penetrate the enclosure.**

### **What to do**

**Cease use of the luminaire.**

**Owners of an affected luminaire having a serial number within the specified production batch, are with this announcement invited to contact their point of purchase.**

**After providing relevant details, you should return your luminaire to the point of purchase in order to have the product repaired or replaced free of charge.**